








Mounting instruction



Ecoflex[®] 10 Plus, Aircom[®] Premium

N socket crimp / Item no.: 7370

www.ssb-electronic.com

Required tools:	
1 x	cutter knife
1 x	scissors
1 x	crimping tool
1 x	crimp insert HEX .429 (10,9 mm)
1 x	crimp insert HEX .127 (3,25 mm)
1 x	soldering station + solder
1 x	heat gun
1	 Cut off cable tail right-angled. Slide the crimp sleeve and the heat-shrink tubing over the end of the cable. Remove 17 mm of the outer jacket with the knife.
2	 Bend the copper braid up at right angle. Score and remove 8 mm of the copper foil with the cutter knife.
3	 Then score and remove 4 mm of the foamed dielectric with a cutter knife.
4	 Push the inner pin onto the conductor and crimp or solder through the hole. Hint: Pin 1: 2,8 mm Ø Aircom Premium Pin 2: 3,0 mm Ø Ecoflex 10.
5	 Insert the so prepared cable end into the connector housing as far as it will go (click). Bend the copper braid up at a right angle and cut it off with scissors. Slide the sleeve up to the stop.
6	 Crimp the crimp sleeve with the crimping tool. This will clamp the copper braid between the connector housing and the crimp sleeve.
7	 Push the heat-shrink tubing forward until it stops, heat it up with the heat gun and let it shrink.